

ShowMax® Set Up



1 Place Showmax unit on your display table with wheels facing up and away.



2 Unlatch and open unit. Remove header and lights.



3 Before raising the display, unlatch endcaps from the unit.



4 Fold up the wheel endcaps. This creates a flat surface at the bottom of the display.



5



Grip the handles and lift case to vertical. Fold back handle endcaps.



6

Open outer panels. Leave them angled slightly.



7

Place header into two slots on backside of center panels.



8

Mount light fixtures. Insert base pegs into holes on the top of the side panels.

Visit GoEXPOGO.com

ExpoGo!
ExpoStar·Presenta·ArchiForm

(800)-891-1869